



FLIGHT DESIGN

№ 080128

Flight Design Manufacturer Approval

for CTSW, S/N: 06-10-04

We approve installation of the 2" Thermo-Tec header wrap, based on the photos below. The wrap of the exhaust pipes reduces accessibility to inspection for cracks on the exhaust pipe. Such cracks may lead to exhaust fumes coming into the cabin. Therefore it is in the obligation of the owner / modifier to ensure that the exhaust pipes are inspected for condition at the intervals defined for this aircraft, regardless of the reduced accessibility.



Note: Approval is given for the mechanical installation only. Correct function of all installed equipment is under the obligation of the modifier as this can not be checked by Flight Design.

Flight Design Document Center, 28 Jan 2008

It's up to you.

